Declassified in P	Part - Sanitized Copy Approved for Release 2013/08/14 : CIA-RDP78-03624A00	
		50X1
~		50X1
	14 October 1957	REFER TO:
		SERIAL No. 7975
	tis decument is part of an integrated le. It separated from the file it must be subjected to individual systematic registre 3 -2 6	50X1
	le. It separated from the line to the subjected to individual systematic registro	
		016
	DOCUMENT NO	то: тs s c
	Attention: NEXT REVIEW DATE AUTH: HR 70-2	
	DATE:	REVIEWER: 006657
		50X1
	1 5122277 Hoist Assembly 1 5125787 Beam Assembly 1 4155968 Socket Assembly 1 4128221 Support Bracket	30/(1
	• • • • • • • • • • • • • • • • • • •	
	2. It is not anticipated that an additional Beam Assembly (5125787) will be required for use on this project. The intended use of the one Beam Assembly requested was for preliminary design and development work on a beam assembly that would better fit our particular hoisting requirements.	
	3. This project eventually will need an additional Hoist (5122277), Socket (4155968), and Support (4128221). Request for this stock will be made at a later date.	
	4. Attention is called to the fact that no handle or crank was supplied with the Hoist Assembly (5122277). The Douglas reference blueprint shows this call-out of the handle to be:	
v.	"AC35B3441 Handle Assembly (Ref.) furnished with 36H5311 Hoist Assembly called for on 5152260 & -1."	
•	5. Inasmuch as the crank is comparatively simple to fabricate, we intend to take care of this requirement without further request for this item from other sources.	
	Very truly,	
		50X1
		50X1
		`
	Assistant to the President	
	JS:cb	
		